



Feed and Support Kit Contents



FEED KIT CONTENTS:

- One (1) 72" Feed Cord
- One (1) 4" Canopy
- One (1) Grommet
- One (1) Threaded Barrel
- One (1) 72" Swaged Suspension Cable
- One (1) Y-Cable Assembly with Cable Gripper and Snap-lock Connectors
- Two (2) #8 x 5/8" Screws
- One (1) Strain Relief
- One (1) Hog Ring




SUPPORT KIT CONTENTS:

- One (1) 2" Canopy
- One (1) Threaded Barrel
- One (1) 72" Swaged Suspension Cable
- One (1) Y-Cable Assembly with Cable Gripper and Snap-Lock Connectors

Feed Kit Installation



Slide power cord through feed canopy and make electrical connections to pre-installed junction box.



Insert swaged suspension cable through threaded barrel.




Secure feed canopy to 1/4-20 x 1 1/2" length stud (not included) with threaded barrel.

Product to be installed by qualified electrician only.

Separation of circuits in the outlet box are to be made in accordance with local and/or national electrical installation codes.

PART #110859-2

Support Kit Installation (non-feed locations)




1
Insert swaged suspension cable through threaded barrel.




2
Secure non-feed canopy to 1/4-20 x 1 1/2" length stud (not supplied) with threaded barrel.

Suspending the Fixtures



1
Insert suspension cables into support barrels and adjust to appropriate length. Tighten knurled knob to fix in place.



2
Adjust housing so it is level and tighten set screw to fix position.


Note: Luminaires must be tied to structure per local requirements.

Product to be installed by qualified electrician only.


Separation of circuits in the outlet box are to be made in accordance with local and/or national electrical installation codes.

PART #110859-2


Electrical Connection at Feed End



Remove ballast channel cover by releasing the snap-fit, then using the male/female Molex connectors, make the electrical power connection. channel.



Install strain relief consisting of small metal plate and 2 screws, making sure the hog ring on the feed cord is on the side of the strain relief toward the center of the fixture.



Attach feed wire to the fixture housing and cable supports for clean appearance. Reinstall channel cover.

Complete Hanging Assembly- Examples



Light Screen



Fabric Shield

Product to be installed by qualified electrician only.

Separation of circuits in the outlet box are to be made in accordance with local and/or national electrical installation codes.

PART #110859-2